

ADA 039848

(12)

K
AD

TECHNICAL REPORT ARLCB-TR-77028

THE ABRASION CHARACTERISTICS OF CERTAIN PROTECTIVE
COATINGS ON ALUMINUM AND MAGNESIUM ALLOYS

A. Campbell
W. Mortimer
P. Thornton


May 1977



US ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND
LARGE CALIBER WEAPON SYSTEM LABORATORY
BENET WEAPONS LABORATORY
WATERVLIET, N. Y. 12189

AMCMS No. 3297.06.7234

PRON No. M1-3-23021-01-M7-M7



APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED

Re. No.

DDC FILE COPY

DISCLAIMER

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

The use of trade name(s) and/or manufacturer(s) in this report does not constitute an official indorsement or approval.

DISPOSITION

Destroy this report when it is no longer needed. Do not return it to the originator.

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER ARLCB-TR-77028	2. GOVT ACCESSION NO. DTIC- Technical report.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) The Abrasion Characteristics of Certain Protective Coatings on Aluminum and Magnesium Alloys.	5. TYPE OF REPORT & PERIOD COVERED	
6. AUTHOR(s) A. Campbell, W. Mortimer P. Thornton	7. PERFORMING ORG. REPORT NUMBER	
8. PERFORMING ORGANIZATION NAME AND ADDRESS Benet Weapons Laboratory Watervliet Arsenal, Watervliet, N.Y. 12189 DRDAR-LCB-TL	9. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS AMCAMS No. 3297.06.7234 Prop No. M1-3-23021-01-M7-M7	
10. CONTROLLING OFFICE NAME AND ADDRESS US Army Armament Research and Development Command Large Caliber Weapon System Laboratory Dover, New Jersey 07801	11. REPORT DATE 11 May 1977	
12. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)	13. NUMBER OF PAGES 12171	
14. DISTRIBUTION STATEMENT (of this Report)	15. SECURITY CLASS (of this report) UNCLASSIFIED	
Approved for public release; distribution unlimited.	16. DECLASSIFICATION/DOWNGRADING SCHEDULE	
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)	18. SUPPLEMENTARY NOTES	
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Abrasion Anodic Coatings Films		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The abrasion resistances of two finishing systems, one applied to 2014 aluminum and the other to ZK60A magnesium, were evaluated. Both alloys were first anodized. Subsequently, a blue-wash primer and semigloss paint were applied to the 2014 aluminum; the ZK60A magnesium received a polyamide primer and a polyurethane topcoat. The tests, performed to compare the relative abrasion resistances of the two systems, were carried out using the Taber Abraser Model 503. Abrasion rates were measured by a weight-loss technique. (See reverse side)		

DD FORM 1 JAN 73 1473 EDITION OF 1 NOV 68 IS OBSOLETE

410 163

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

Block 20 (cont)

Analysis of the data indicated that, under the test conditions applied, the topcoats contributed little to the overall abrasion resistance of the two coating systems; rather, the anodic layer of each appeared to be the most important parameter. Further, the rate of abrasion of the anodic layer was relatively constant in each case and could be approximated by a straight line relationship. The anodic film on the 2014 aluminum demonstrated significantly better resistance to abrasion than that on the ZK60A magnesium.

TABLE OF CONTENTS

	Page
Introduction	1
Objective	2
Procedure	2
Results and Discussion	4
Conclusions	6
References	7

LIST OF TABLES

1. Abrasion Rate - Medium Abrader	8
2. Abrasion Rate - Heavy Abrader	9

LIST OF FIGURES

1. Taber Abraser Model 503	10
2. Typical Wear Track on Test Specimens	10
3. Typical Abrasion Curve - Aluminum	11
4. Typical Abrasion Curve - Magnesium	12
5. Layers in 2014 Aluminum Film	13
6. Layers in ZK60A Magnesium Film	13

White Section	<input checked="" type="checkbox"/>
Dark Section	<input type="checkbox"/>
Specimen No.	100-1000
Specimen Date	10-10-1989
EQUIPMENT/AVAILABILITY CODES	
USE	AVAIL. ACC. OR SPECIAL
A	

INTRODUCTION

Lightweight, nonferrous alloys are frequently used in structural applications to utilize their high strength-to-weight ratios. In particular, aluminum and magnesium alloys are widely used for this purpose. There are presently several alloys in each system that demonstrate adequate strength and ductility for certain low-medium strength weapon applications.

The magnesium (Mg) alloys have significantly lower densities than the aluminum (Al) alloys and are, therefore, very attractive. However, a serious drawback to the utilization of the Mg alloys is their susceptibility to corrosion and stress corrosion^{1,2,3}. This problem is dealt with by protectively coating the Mg alloys, especially in critical applications, by anodizing and painting. The corrosion resistance of various finishing systems on Mg has been investigated by Sandler^{4,5} and Brown⁶. One system that displayed excellent corrosion resistance was a combination of DOW-17 anodize (MIL-M-45202) with epoxy polyamide primer (MIL-P-23377) and polyurethane topcoat (MIL-C-81773). Anodized and painted aluminum alloys have also been found to be highly resistant to corrosion⁵.

In service, however, the corrosion resistance of a protective finishing system is not the only important criterion; the abrasion resistance of the coating must also be considered because, as the thickness of the "film" diminishes through wear, its protective abilities also decrease. The best corrosion-resistant coating system

can be rendered ineffective if it exhibits poor resistance to abrasion.

OBJECTIVE

The purpose of this study was to evaluate the abrasion characteristics, both qualitatively and quantitatively, of two specific finishing systems, one applied to an aluminum alloy and the other to a magnesium alloy. The two systems were similar in that they both contained an anodic layer, whereas the topcoats were somewhat dissimilar. Abrasion information of this nature will assist in predicting the useful service life of components that are manufactured from the respective alloys and receive these coating systems.

PROCEDURE

Test specimens, 102mm x 102mm x 1.6mm (4" x 4" x 1/16") were prepared from 2014 aluminum alloy and ZK60A magnesium alloy stock. These plates were machined and ground to dimension. The finishing systems were applied as follows:

A. Anodizing - The aluminum alloy specimens were anodized by the sulphuric acid process per ASTM Standard B580, while the DOW-17 process was used to anodize the ZK60A specimens per MIL-M-45202.

B. Priming - The anodized specimens were immediately primed; the 2014 plates received a blue wash primer per MIL-P-15328C and the ZK60A plates were coated with epoxy-polyamide per MIL-P-23377.

C. Painting - The 2014 plates were sprayed with a semigloss enamel paint (Federal Specification TT-E-485F); the ZK60A specimens were given a polyurethane topcoat (MIL-C-81773).

The finished specimens were tested on a Taber Abraser Model 503 (Figure 1) utilizing both the CS-10 and H-10 wheels at a constant load of 500 grams. The CS-10 Calibrase, a resilient, medium abrasive, wheel is designed to simulate the mild abrasion experienced in normal handling, cleaning, and polishing. The H-10 Calibrase, a non-resilient, vitrified wheel, is a much harsher abrasive. The rate of abrasion was determined by the weight loss technique. The weight (w) of each specimen was initially recorded and then measured periodically throughout the test. This data was plotted versus the respective number of cycles. The slope of the curve (dw/dN) at any point is the instantaneous rate of abrasion, while the average slope of the curve over the period of a particular layer, e.g., anodic film, was considered to be the abrasion rate in that layer.

Testing was continued until a significant breakthrough to the base metal was visually observed. Also, breakthroughs to the primer and anodic film were recorded. As the data will show, the section of the curves corresponding to the abrasion of the anodic film fits a straight line relationship. Therefore, this portion of the data was subjected to a linear regression analysis and the slope, intercept and correlation coefficient were calculated for each specimen.

This type of behavior, i.e., relatively constant wear resistance, has been previously recognized in anodized aluminum⁷.

RESULTS AND DISCUSSION

During testing, the topcoats (paint and primer considered together) were worn away in relatively few cycles and contributed little to the overall abrasion resistance of the coatings. Rather, the abrasion characteristics of the anodic layers was the important parameter. A wear track, illustrative of those formed on the tested specimens, is shown in Figure 2. Typical abrasion curves for the two systems are illustrated in Figures 3 and 4.

For a particular set of conditions (load and abrader) the anodic film on the 2014 aluminum alloy exhibited significantly better abrasion resistance than that on the ZK60A magnesium alloy. No doubt, this behavior is associated with the fact that aluminum oxide is considerably harder than magnesium oxide. Other investigators have reported abrasive wear to be roughly proportional to the hardness of the abraded material⁸⁻¹⁰.

The abrasion rates for the anodic layers, as determined by the linear regression analysis, are given in Tables 1 and 2. As shown, the anodized magnesium abrades at 11.2 micrograms per cycle or approximately 11 times the rate of the anodized aluminum under the "medium abrasive" conditions, while it abrades at 67.2 micrograms per cycle or about 4 times the rate of the anodized aluminum for the "heavy abrasive"

condition. As was expected, the rate of abrasion of the two anodic films increased with the severity of the abrasive surface. However, the increase in abrasion rate was not proportioned; the wear rate of aluminum increased significantly more than that of the magnesium under the "heavy abrasive" condition. Perhaps this anomalous behavior can be attributed to the clogging of the H-10 wheels with the material being abraded. Abrasion would then result not only from the wheel, but also from the oxide being picked up. Alumina is the harder of the two oxides, so it is therefore likely that the abrasive effect of alumina on itself was greater than the self-abrasion of the magnesia. This phenomenon was not as serious a problem when using the CS-10 wheels as equipment was available to dress the wheels periodically.

The anodic film formed on the 2014 aluminum was evidently more uniform in composition than the magnesium anodized film. This was observed by noting color changes in the films during abrasive testing and by cross-sectional examination of the respective coatings (Figures 5 and 6). The anodized magnesium contained two distinct layers of different hardness which could have contributed to the slightly poorer straight line fit of the magnesia than the alumina as evidenced by the R (correlation coefficient) values (Tables 1 and 2). Nevertheless, the R values do indicate that the straight-line approximation is valid for both the alumina and magnesia and that their abrasion behavior can be expressed as the slopes of these lines.

It should be emphasized that the accuracy of this approach to measuring abrasion rates in protective coatings depends somewhat on the judgment and interpretation of the investigator. Specifically, determination of the "breakthrough" point between the varicous layers is quite subjective. Also, the operator must decide how often to reface the abrasive wheels in order to obtain reliable abrasion data with a minimum of scatter.

An alternative to the weight-loss technique would be a measurement of the change in thickness of the coating periodically during cycling. The film thickness on ferromagnetic materials can be measured by magnetic methods (viz Nordson Film Gauge); an eddy-current type device can be used for similar determinations on nonferrous materials.

CONCLUSIONS

Based on the results obtained in this investigation, the following conclusions are permitted:

1. The topcoat layers of primer and paint do not play a significant role in the abrasion resistance of these coatings.
2. The abrasion rate of the anodized aluminum was considerably lower than the rate of anodized magnesium for the same load and abrader.
3. The abrasion rate of the anodic film, on both Al and Mg as determined by the weight loss technique, can be expressed as the slope of the straight line portion of the abrasion curve (weight vs cycles), corresponding to the anodic region.

REFERENCES

1. Uhlig, H.H., "The Corrosion Handbook", p. 218, John Wiley & Sons, New York, 1948.
2. Uhlig, H.H., "Corrosion and Corrosion Control", p. 295, John Wiley and Sons, New York, 1963.
3. Fontana, M.G. and Greene, N.D., "Corrosion Engineering", p. 170, McGraw-Hill, New York, 1967.
4. Sandler, M.H., and Cohen, M., "Tropical Exposure of Finishing Systems for Aluminum and Magnesium", CCL Report No. 233, Aberdeen Proving Ground, September 1967.
5. Sandler, M.H., "Seven Years Tropical Exposure of Finishing Systems for Aluminum and Magnesium", CCL Report No. 319, Aberdeen Proving Ground, November 1972.
6. Brown, S.R., "Protective Finishing Systems for Magnesium Aircraft Components", NADC-MA-7102, Naval Air Development Center, 7 July 1971.
7. Pritchard, C. and Robinson, P.P., Wear, 13, (1969), p. 361.
8. Bowden, F.P. and Tabor, D., "The Friction and Lubrication of Solids", Part II, Clarendon Press, Oxford, 1964.
9. Rabinowicz, E., "Friction and Wear of Materials", John Wiley & Sons, New York, 1965.
10. Khruscher, M.M. and Babicher, M.A., Russ. Engr. J., 44, (6), 1964, p. 43.

TABLE 1. ABRASION RATE - MEDIUM ABRADER

ALUMINUM

<u>Specimen</u>	<u>dw/dN (micrograms/cycle)</u>	<u>R</u>
1	1.45	.992
2A	0.73	.996
2B	1.07	.990
Average	1.08 ± 0.36	

MAGNESIUM

<u>Specimen</u>	<u>dw/dN (micrograms/cycle)</u>	<u>R</u>
1A	12.3	.991
1B	11.6	.989
2A	10.7	.988
3A	10.2	.983
Average	11.2 ± .93	

CS-10 WHEELS

500 GRAM LOAD

R - Correlation Coefficient
Straight Line Regression

TABLE 2. ABRASION RATE - HEAVY ABRADER

ALUMINUM

<u>Specimen</u>	<u>dw/dN (micrograms/cycle)</u>	<u>R</u>
3A	10.9	.995
3B	18.1	.997
5	19.1	.998
Average	16.0 \pm 4.47	

MAGNESIUM

<u>Specimen</u>	<u>dw/dN (micrograms/cycle)</u>	<u>R</u>
4A	65.7	.998
5	68.3	.987
6	67.6	.984
Average	67.2 \pm 1.35	

H-10 WHEELS
500 GRAM LOAD

R - Correlation Coefficient
Straight Line Regression




Figure 1. Taber Abraser Model 503.




Figure 2. Typical wear track of test specimen (1 Al).

- a. Abraser
- b. Abrasion track
- c. Wear track




Figure 3. Typical abrasion curve - aluminum.




Figure 4. Typical abrasion curve - magnesium.




Figure 5. Layers in 2014 aluminum film.

- a. Paint
- b. Primer
- c. Anodic layer
- d. Base metal




Figure 6. Layers in ZK60A magnesium film.

- a. Topcoat
- b. Anodic film showing several layers
- c. Base metal

WATERVLIET ARSENAL INTERNAL DISTRIBUTION LIST

May 1976

	<u>No. of Copies</u>
COMMANDER	1
DIRECTOR, BENET WEAPONS LABORATORY	1
DIRECTOR, DEVELOPMENT ENGINEERING DIRECTORATE	1
ATTN: RD-AT	1
RD-MR	1
RD-PE	1
RD-RM	1
RD-SE	1
RD-SP	1
DIRECTOR, ENGINEERING SUPPORT DIRECTORATE	1
DIRECTOR, RESEARCH DIRECTORATE	2
ATTN: RR-AM	1
RR-C	1
RR-ME	1
RR-PS	1
TECHNICAL LIBRARY	5
TECHNICAL PUBLICATIONS & EDITING BRANCH	2
DIRECTOR, OPERATIONS DIRECTORATE	1
DIRECTOR, PROCUREMENT DIRECTORATE	1
DIRECTOR, PRODUCT ASSURANCE DIRECTORATE	1
PATENT ADVISORS	1

EXTERNAL DISTRIBUTION LIST

December 1976

1 copy to each

OFC OF THE DIR. OF DEFENSE R&E
ATTN: ASST DIRECTOR MATERIALS
THE PENTAGON
WASHINGTON, D.C. 20315

CDR
US ARMY ARMT COMD
ATTN: AMSAR-PPW-IR
AMSAR-RD
AMSAR-RDG

ROCK ISLAND, IL 61201

CDR
US ARMY TANK-AUTMV COMD
ATTN: AMDTA-UL
AMSTA-RKM MAT LAB
WARREN, MICHIGAN 48090

CDR
US ARMY ARMT COMD
FLD SVC DIV
ARMCOM ARMT SYS OFC
ATTN: AMSAR-ASF

ROCK ISLAND, IL 61201

CDR
PICATINNY ARSENAL
ATTN: SARPA-TS-S
SARPA-VP3 (PLASTICS
TECH EVAL CEN)
DOVER, NJ 07801

CDR
US ARMY ELCT COMD
FT MONMOUTH, NJ 07703

CDR
FRANKFORD ARSENAL
ATTN: SARFA
PHILADELPHIA, PA 19137

CDR
REDSTONE ARSENAL
ATTN: AMSMI-RRS
AMSMI-RSM
ALABAMA 35609

DIRECTOR
US ARMY BALLISTIC RSCH LABS
ATTN: AMXBR-LB
ABERDEEN PROVING GROUND
MARYLAND 21005

CDR
ROCK ISLAND ARSENAL
ATTN: SARRI-RDD
ROCK ISLAND, IL 61202

CDR
US ARMY RSCH OFC (DURHAM)
BOX CM, DUKE STATION
ATTN: RDRD-IPL
DURHAM, NC 27706

CDR
US ARMY FGN SCIENCE & TECH CEN
ATTN: AMXST-SD
220 7TH STREET N.E.
CHARLOTTESVILLE, VA 22901

CDR
WEST POINT MIL ACADEMY
ATTN: CHMN, MECH ENGR DEPT
WEST POINT, NY 10996

DIRECTOR
US ARMY PDN EQ. AGENCY
ATTN: AMXPE-MT
ROCK ISLAND, IL 61201

CDR
HQ, US ARMY AVN SCH
ATTN: OFC OF THE LIBRARIAN
FT RUCKER, ALABAMA 36362

/

EXTERNAL DISTRIBUTION LIST (Cont)

1 copy to each

CDR
US NAVAL WPNS LAB
CHIEF, MAT SCIENCE DIV
ATTN: MR. D. MALYEVAC
DAHLGREN, VA 22448

DIRECTOR
NAVAL RSCH LAB
ATTN: DIR. MECH DIV
WASHINGTON, D.C. 20375

DIRECTOR
NAVAL RSCH LAB
CODE 26-27 (DOCU LIB.)
WASHINGTON, D.C. 20375

NASA SCIENTIFIC & TECH INFO FAC
PO BOX 8757, ATTN: ACQ BR
BALTIMORE/WASHINGTON INTL AIRPORT
MARYLAND 21240

DEFENSE METALS INFO CEN
BATTELLE INSTITUTE
505 KING AVE
COLUMBUS, OHIO 43201

MANUEL E. PRADO / G. STISSER
LAWRENCE LIVERMORE LAB
PO BOX 808
LIVERMORE, CA 94550

DR. ROBERT QUATTRONE
CHIEF, MAT BR
US ARMY R&S GROUP, EUR
BOX 65, FPO N.Y. 09510

2 copies to each

CDR
US ARMY MOB EQUIP RSCH & DEV COMD
ATTN: TECH DOCU CEN
FT BELVOIR, VA 22060

CDR
US ARMY MAT RSCH AGCY
ATTN: AMYMR - TECH INFO CEN
WATERTOWN, MASS 02172

CDR
WRIGHT-PATTERSON AFB
ATTN: AFML/MXA
OHIO 45433

CDR
REDSTONE ARSENAL
ATTN: DOCU & TECH INFO BR
ALABAMA 35809

12 copies

CDR
DEFENSE DOCU CEN
ATTN: DDC-TCA
CAMERON STATION
ALEXANDRIA, VA 22314

NOTE: PLEASE NOTIFY CDR, WATERVLIET ARSENAL, ATTN: SARWV-RT-TP,
WATERVLIET, N.Y. 12189, IF ANY CHANGE IS REQUIRED TO THE ABOVE.